Oil Field Environmental Incident Summary

Responsible Party: Oxy USA Inc **Well Operator:** OXY USA INC. **Well Name:** MARTIN 34-31H

Field Name: CABERNET Well File #: 18193

Date Incident:2/7/2014Time Incident:0800Facility ID Number:County:DUNNTwp:144Rng:96Sec:31Qtr:

Location Description:

Submitted By: Dustin Tescher Received By:

Contact Person: Dustin Tescher

5 GREENWAY PLAZA STE 110 HOUSTON, TX 77046-0506

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:0.75 MilesDistance Nearest Water Well:0.75 Miles

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units	
Oil	0	barrels	0	barrels			
Brine	1.5	barrels	0.5	barrels	0.5	barrels	
Other	0	barrels	0	barrels			

Description of Other Released Contaminant:

Inspected: Written Report Received: 4/30/2014 Clean Up Concluded: 3/31/2014

Risk Evaluation:

Areal Extent:

Potential Environmental Impacts:

Contaminated surface material inside containment berm

Action Taken or Planned:

The tank level was lowered to stop the release and all standing fluid was recovered.

Wastes Disposal Location: Cabernet SWD

Agencies Involved:

Updates

Date: 2/10/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from an on-location pipeline leak remained on location within the diking, according to the report. NDIC retains oversight.